

**Municipality of Huron-Kinloss
Point Clark Water Quality Monitoring Program
2017 Sampling Results**

E. Coli (cfu/100mL)

SAMPLE ID	LOCATION	Sample Date														
		25-Apr	8-May	23-May	6-Jun	19-Jun	4-Jul	17-Jul	31-Jul	14-Aug	28-Aug	11-Sep	25-Sep	10-Oct	23-Oct	6-Nov
B1	Beach at 917 Cedar Trail	32	38	118	10	126	< 2	44	10	6	< 2	6	28	130	116	282
B2	Beach at Lighthouse swimming area -- same as PR22	10	60	30	32	40	< 2	26	2	2	4	14	2	90	20	420
B3	Beach at 755 Victoria	4	26	26	30	54	4	40	2	4	2	6	< 2	92	16	374
B4	Clark Creek at the Lake	92	10	146	206	800	64	148	34	32	24	720	54	294	278	1000
4	Jardine Creek at Walpole Trail	2	10	142	38	284	212	154	46	68	312	78	6	32	10	392
5	Ditch at field drain outlet, Lake Range Road	16	720	40	110	840	334	1000	Dry	Dry	Dry	2240	Dry	Dry	1840	294
6	New outlet to Clark Creek across from 3491 2nd Conc.	16	18	122	176	1280	540	324	124	64	ns	600	62	32	126	680
8	Jardine Creek at Abenaki St.	60	94	172	28	98	72	144	50	30	278	48	Stagnant	2	2280	64
9	Jardine Creek at Seneca	10	48	26	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	2	Dry	34
11	Off foot bridge at beach	600	70	960	224	760	420	102	262	192	174	112	1000	256	840	228
12	Halfway to lake from Road	6	16	78	116	232	284	150	84	100	46	32	50	12	14	82
13	CSP where creek crosses Huron Rd.	4	64	202	84	276	154	196	560	150	2080	42	68	58	30	50
16	Outlet at Lake Range Dr. and Attawandaron Rd.	10	2	236	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry
17	Outlet in Jardine Creek between sites 11 & 12	98	18	920	124	336	288	54	140	242	294	206	1400	1920	1960	1160
14	Jardine Creek CSP north of 8	n/s	n/s	198	4	20	Dry	150	Dry	Dry	Dry	Dry	Dry	Dry	Dry	280
15	Jardine Creek CSP north of 14	n/s	n/s	4	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry	Dry

n/s = no sample